

2699 East CR 50 Tiffin. OH 44883 Tiffin Office: 419-618-3072 Fax: 419-443-0539 Huntsville Office: 937-539-0094 Fax 937-843-3079

hhenvironmental@yahoo.com



Asbestos Survey

820 S. Detroit St; Bellefontaine, OH 43311

LUC Regional Planning Commission



2699 East CR 50 Tiffin. OH 44883 Tiffin Office: 419-618-3072 Fax: 419-443-0539 Huntsville Office: 937-539-0094 Fax 937-843-3079 hhenvironmental@yahoo.com

LUC Regional Planning Commission

11/6/23

10820 SR 347

East Liberty, OH 43319

Phone:937-666-3431

Email: heathermartin@lucplanning.com

Heather Martin

Asbestos survey: 820 S. Detroit St; Bellefontaine, OH 43311

Heather,

H&H Environmental, LLC. has completed an inspection for asbestos-containing materials (ACM) at 820 S. Detroit; Bellefontaine, OH 43311. This inspection was performed by Tyler Rister (Certification # 35958) and Jace Hurt (Certification # 36450) on October 27th, 2023 in Bellefontaine, OH. Tyler Rister and Jace Hurt maintain a current Ohio EPA Asbestos Inspector Certifications. Proof of these certifications are attached.

Enclosed:

- 1. Asbestos Survey Cover
- 2. Asbestos Survey Letter
- 3. Purpose and Procedure
- 4. ACM Summary and Notice
- 5. Sample Chain-of-custody
- 6. Sample Site Pictures
- 7. Laboratory Analysis Report (and point-count analysis if applicable)
- 8. Asbestos Inspector Certifications

Purpose of Inspection:

The ACM inspection was conducted in accordance and observation of EPA NESHAP and OSHA regulations pertaining to the demolition/renovation of regulated structures. This inspection included all applicable and accessible areas of the structure.

Procedure:

The inspection, conducted on 10-27-2023, was completed utilizing applicable Federal and Ohio State regulations pertaining to asbestos: Federal OSHA (29 CFR 1910.1001and 29 CFR 1926.1101), EPA (40 CFR Part 61), and TSCA Title II AHERA/ASHARA (40 CFR Part 763) Asbestos Regulations. The findings in this report are consistent with accepted principles and practice established and prescribed by the EPA and AHERA.

All accessible areas of the building in Bellefontaine, OH were inspected physically, functional space by functional space, and homogeneous area by homogeneous area to determine the presence of asbestos-containing materials. Suspected asbestos-containing materials were grouped per homogeneous area. Suspect materials that may be present inside wall cavities, electrical wiring or which were otherwise inaccessible were not included in the scope of this inspection. Core samples of friable and non-friable suspect asbestos-containing materials were collected to be analyzed for asbestos content. Those materials considered to be non-suspect (concrete, wood, fiberglass, carpeting, metal, etc.) were not sampled for analysis. Each location for sample collection, chosen at random, were representative of the suspect materials. The bulk samples were placed in zip-lock bags, sealed, and labeled with an identifying code. The samples, along with the chain-of-custody, were then submitted to the laboratory, McCall and Spero Environmental, Inc., to be analyzed for asbestos content. A copy of the chain-of-custody is attached.

12 bulk samples of suspected ACM, were submitted to a laboratory for analysis using Polarized Light Microscopy. Laboratory results are attached.

Analytical Results:

H&H Sample # Lab Sample #	Homogenous Area	Layers	Description/ Sample Location	PLM Result
			Swiipio zouwion	
820-01	1	2	Drywall/Compound Rm.7	ND
PO313HHE.4-01			Wall A/D	
820-02	1	2	Drywall/Compound Rm.3	ND
PO313HHE.4-02			Wall C	
820-03	2	1	Window Glaze Rm.8 Wall	ND
PO313HHE.4-03			C	
820-04	2	1	Window Glaze Rm.2 Wall	ND
PO313HHE.4-04			A	
820-05	3	2	Plaster Rm.8 Wall D	ND
PO313HHE.4-05				
820-06	3	2	Plaster Rm.1 Wall A	ND
PO313HHE.4-06				
820-07	3	2	Plaster Rm. 2 Ceiling	ND
PO313HHE.4-07				
820-08	4	2	12" tile/glue (Grey) Rm.3	ND
PO313HHE.4-08			near Wall C	
820-09	4	2	12" tile/glue (Grey) Rm.3	ND
PO313HHE.4-09			near Wall A	
820-10	5	1	Transite Siding outside	15% Chrysotile
PO313HHE.4-10			Rm.4	
820-11	6	1	Asphalt Roofing outside	ND

PO313HHE.4-11			Rm.2	
820-12 PO313HHE.4-12	6	1	Asphalt Roofing outside Rm.1	ND

Summary:

Based the analysis of suspected ACM samples, one of the samples of homogenous areas were determined to be asbestos-containing.

The approximate total of asbestos-containing materials are as follows:

Transite Siding

1,500 Sq.ft.

Among the material noted above, the <u>Transite Siding</u> material must be removed by a licensed asbestos abatement contractor prior to renovation or demolition if it would impact this material.

Under current Ohio standards materials containing less than 1% are not "asbestos containing material". However, this material is still regulated under OSHA and must adhere to wet handling, prompt cleanup, disposal requirements set forth by 29 CFR 1926 as applies to demolition operations involving materials containing less than 1% asbestos.

Notice:

An Ohio EPA Notification of Demolition and Renovation form must be completed and submitted to the Ohio EPA at least ten working days prior to the commencement of any abatement or demolition activity. The amount, type and condition of the asbestos-containing materials found in this inspection, as well as the materials assumed to be asbestos-containing materials, must be noted on the form. The name and certification number of the asbestos inspector must be included.

If any additional materials are encountered in these locations, these materials should be left intact and undisturbed until they can be inspected and and sampled by a licensed Asbestos Abatement Evaluation Specialist. H&H Environmental would be happy to return to the site if additional suspect materials are encountered during demolition activity. The other option is to assume that the material is asbestos-containing and have it abated as such.

This report, and the supporting findings, data, conclusions, and recommendations represents H&H Environmental's efforts on behalf of the client. This report is not an asbestos abatement specification and shouldn't be used for specifying removal techniques or methods. The assessments, conclusions, results, and recommendations stated in this report are representative of the circumstances and conditions observed by the inspector at the date of the inspection. We cannot assume responsibility for any change in conditions or circumstances that occurred after inspection. The findings in this report, if implemented by the client, should not be construed as as an assurance or implied warranty for the continuing safety, performance, or cost-effectiveness of any equipment, system, product, procedure, facility, or policy recommended or discussed herein.

The recommendations in this report are based on the professional judgment of the inspector and the results of the samples collected an analyzed. H&H Environmental makes no warranty, expressed or implied, and accepts no liability for the presence or absence of asbestos or other hazardous materials in or on home products, materials, and areas. H&H Environmental assumes no responsibility for the cost of repairing, removing, or replacing any undiscovered or unreported condition or defect, or any future condition or defect.

If you have any questions or concerns please feel free to contact H&H Environmental's Charles E. Hurt at 419-618-3072.

Thank you,

Tyler Rister Juff

AHES # ES 35958

H&H Environmental

Jace Hurt

AHES # ES 36450

H&H Environmental

H&H Environmental	Asbestos Inspection Work Sheet
Site 820 5. Detroit St. Ci	Bellefontone State OH Zip 43211
	Demolition
Levels: 1 2 3 Attical	Foundation: Slab Crawl Basement Plock
Exterior: Wood Vinyl Aluminum	Asphalt Transite Brick Block
Interior Walls: Drywall Plaster Pane	eling Transite Other
Windows: Wood Ninvl Metal O	other Number //
Flooring: Wood //Concrete 9" Tile	12" The Linoleum Cerume
Heating: FAFHot WaterFurnace Box	ard Duct Work Seam Tape Duct Boots
Roofing: Asphalt Metal Transite	Build Up Other
A 1st Floor	A 2nd Floor
Ceiling Height A Basement	D W W W IS TO SEE THE CEIling Height A Affice
A Basement	W A Attice
D	D B
	•
	W
G	
· ·	W
Inspector Tyler Rister	Certification # ES35958 Date 10/27/25

#	Material	Room Location	Color	Condition	Quantity
	Pryvell/Compand	2,3,6,7	NA	GIF	900 SF
12	Window Calace	1,2,6,7,2, Atia	while/Gran	Calf	11 Windows
#3	1/wh	1-4, 7.8	NA	F	1,300 56
44	12" the/Che	3	Carry	GIF	132 SF
15	Transle giding	Sidny	white	GIF	1,500 SF
16	Alepho It Renting	Ruf	Crucen /8/ack	GIF	1,300 SF
					-
× 01.	orly car remain	for dime	_		
= G00	tons can remain	R = Friable NF = Non Fria			
Power No.	1 Worders × 12	1111	Poster & Day	المد	5 No Sugar
No	Supert Newtong	found			



























































Specialists in Microanalysis

E-mail: customerservice@mselabs.com • Website: www.mselabs.com

Date: October 31, 2023

Attention: Chuck Hurt

H & H Environmental

Subject: Analysis of bulk samples for asbestos mineral fibers by Polarized Light

Microscopy (PLM) with Dispersion Staining (EPA/600/R-93/116)

RE: MSE-PO313HHE.4

820 S. Detroit St; Bellefontaine, OH 43311 Project

Dear Mr. Hurt:

McCall & Spero Environmental, Inc. has completed the analysis of the bulk samples we received from your offices on October 31, 2023. These samples represent the bulk samples from the 820 S. Detroit St; Bellefontaine, OH 43311 Project.

The PLM bulk analysis was performed according to the "Method of the Determination of Asbestos in Bulk Building Materials", R. L. Perkins and B. W. Harvey (EPA/600/R-93/116).

The results for the nineteen (19) samples are summarized in the following report. Please note that for samples consisting of two or more distinct components, each component is analyzed and reported individually (EPA 40 CFR Part 61 [FRL-4821-71]).

Thank you for consulting McCall & Spero Environmental, Inc. Should you have any questions concerning these results, please contact our office.

Sincerely,

Kevin R. Bean, B.A. PLM Laboratory Director



SUMMARY OF PLM BULK ANALYSIS RESULTS

Page 1

Project Name: 820 S. Detroit St; Bellefontaine, OH 43311 Project McCall & Spero Environmental Project No. MSE-PO313HHE.4

MSE # PO313HHE.4	SAMPLE # DESCRIPTION	ASBESTOS TYPE & %	OTHER FIBROUS MATERIAL & %	% NON-FIBROUS MATERIAL	COLOR
001 (A)	820-01 (A) Drywall	ND	Cellulose / 15%	85%	White
001 (B)	820-01 (B) Joint Compound	ND	Cellulose / 3%	97%	White
002 (A)	820-02 (A) Drywall	ND	Cellulose / 15%	85%	White
002 (B)	820-02 (B) Joint Compound	ND	Cellulose / 3%	97%	White
003	820-03 Window Glaze	ND**	Cellulose / 2%	98%	Gray
004	820-04 Window Glaze	ND**	Cellulose / 2%	98%	Gray
005 (A)	820-05 (A) Skim Coat	ND**	Cellulose / 2%	98%	White
005 (B)	820-05 (B) Plaster	ND**	Cellulose / 2% Hair / 5%	93%	Gray
006 (A)	820-06 (A) Skim Coat	ND**	Cellulose / 2%	98%	White
006 (B)	820-06 (B) Plaster	ND**	Cellulose / 2% Hair / 5%	93%	Gray
007 (A)	820-07 (A) Skim Coat	ND**	Cellulose / 2%	98%	White
007 (B)	820-07 (B) Plaster	ND**	Cellulose / 2% Hair / 5%	93%	Gray
008 (A)	820-08 (A) Tile	ND**	Cellulose / 3%	97%	Gray
008 (B)	820-08 (B) Glue	ND**	Cellulose / 3%	97%	Yellow
009 (A)	820-09 (A) Tile	ND**	Cellulose / 3%	97%	Gray

McCall & Spero Environmental, Inc.

SUMMARY OF PLM BULK ANALYSIS RESULTS

Page 2

MSE # PO313HHE.4	SAMPLE # DESCRIPTION	ASBESTOS TYPE & %	OTHER FIBROUS MATERIAL & %	% NON-FIBROUS MATERIAL	COLOR
009 (B)	820-09 (B) Glue	ND**	Cellulose / 3%	97%	Yellow
010	820-10 Transite Siding	CH / 15%	ND	85%	Gray
011	820-11 Asphalt Roofing	ND**	Glass / 15%	85%	Black
012	820-12 Asphalt Roofing	ND**	Glass / 15%	85%	Black

NOTES:

ND = None Detected

CH = Chrysotile

A = Amosite

AC = Actinolite

CR = Crocidolite

AN = Anthophyllite TR = Tremolite

For samples consisting of separate components, each component is analyzed and reported separately.

Results apply only to items tested. Quantification is accurate to within \pm 10%. Results from this report must not be reproduced, except in full, with the approval of McCall & Spero Environmental, Inc. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.

** EPA recommends that bulk materials found negative for asbestos or less than one percent asbestos by polarized light microscopy that fall into one of five dominantly nonfriable categories be reanalyzed by an additional method, such as transmission electron microscopy. (EPA Notice of Advisory, FR Vol. 59, No. 146 & Test Method EPA 600/ R-93/116).

Analyst: Kevin R. Bean, B.A.

McCall & Spero Environmental, Inc.

1831 Williamson Court • Suite 100 • Louisville, KY 40223 Phone (502) 244-7135 • (800) 841-0180 • FAX (502) 244-7136

E-mail: customerservice@mselabs.com • Website: www.mselabs.com

BULK SAMPLE CHAIN OF CUSTODY FORM

Company:	H&H Environmental Telephone # 4	419-618-3072 Fax #: 419-443-0)539
Contact:	Chuck Hurt :	Client Project Number:	
Relinquished b	y: Tyler Rister	Date: /0/27/23 Time: /-	<u></u>
Written Repor	t To: Ike Hurt		
Project Name:	820 5 Peterit St. 7	Felletentome OH 43711	
Turn-Around (Circle One): Same Day 24 Hour 2-3 [Day 4-5 Day Weekend Rush A	fter Hour Rush
Analysis Reque	ested (Circle Ope): PLM Bulk Analysis T	M Qualitative Analysis TEM Quantitative A	nalysis (4-5 Day)
For Laboratory	Use Only		
	po313HHE.4	Method: EPA/600/R-93/116	
Samples Receiv	red by: 2 2 2 2	Date: 10/31/23 Time: 6	w_
Client Sample	Location	Sample Description	Sampled By
Number			Sampled by
820.01		well AID	<u> </u>
820.02	Viywall Compound 100m 3 W	ell C	
820-03	Wrader Galage Jour 8 1	of C	
820-04	Window Gloze 1com Z w	COL A	
820-05	Planter 100m 8 Wall D		
820-04	Close 1 com 1 well A		
920.07	Plaster 100m 2 celling		
820.08	12" file/Colve (Corey) /our	3 new well C	
820.09	12 tile/Calve (Grey) 1000	3 NEON WALL A	
820.10	Nonsite Tolang outside 10.	m 4	
820-01	Aspholt Rosting outsile 100	n Z	
820-12	Asholt Roofing outside 1	iom (
	/		



Asbestos Building Inspector Refresher

Certificate

This is to certify

Tyler Rister

XXX-XX-1478



section 855.120 of Title 77. IDPH recognition based on student request. Refresher and has passed an examination in that course with a minimum score of 70% or better. Training was in accordance with 40 CFR Part 763 has attended and successfully completed the Asbestos Hazard Emergency Response Act mandatory course for the Asbestos Building Inspector Indiana requirements under 326 IAC 18-2 and Chapter 3745-22 Ohio Administrative Code, and the Illinois Department of Public Health (IDPH) under (AHERA). The above student received the requisite training for asbestos accreditation under Title II of the Toxic Substances Control Act and State of

Course Location	Examination Date	Date(s) of Course	Expiration Date	Training Manager
Columbus, OH	11/30/2022	11/30/22	11/30/23	Less St.

33150 Lakeland Blvd. Cleveland, OH 44095 www.TSltraining.com

Course Certificate No.

22 TSI 418145 ir

5

TRAINING SERVICES INTERNATIONAL

Asbestos Management Planner Refresher

Certificate

Thus is to certify

Tyler Rister

XXX-XX-1478



has attended and successfully completed the Asbestos Hazard Emergency Response Act mandatory course for the Asbestos Management Planner Refresher and has passed an examination in that course with a minimum score of 70% or better. Training was in accordance with 40 CFR Part 763 section 855.120 of Title 77. IDPH recognition based on student request. Indiana requirements under 326 IAC 18-2 and Chapter 3745-22 Ohio Administrative Code, and the Illinois Department of Public Health (IDPH) under (AHERA). The above student received the requisite training for asbestos accreditation under Title II of the Toxic Substances Control Act and State of

Course Location	Examination Date	Date(s) of Course	Expiration Date	Training Manager
Columbus, OH	11/30/2022	11/30/22	11/30/23	As Cal

33150 Lakeland Blvd. Cleveland, OH 44095 www.TStraining.com

Course Certificate No. 2

22 TSI 418151 mpr



Asbestos Contractor Supervisor Refresher

Certificate

This is to certify

Tyler Rister

XXX-XX-1478



has attended and successfully completed the Asbestos Hazard Emergency Response Act mandatory course for the Asbestos Contractor Supervisor section 855.120 of Title 77. IDPH recognition based on student request Indiana requirements under 326 IAC 18-2, Chapter 3745-22 Ohio Administrative Code, and the Illinois Department of Public Health (IDPH) under (AHERA). The above student received the requisite training for asbestos accreditation under Title II of the Toxic Substances Control Act, State of Refresher and has passed an examination in that course with a minimum score of 70% or better. Training was in accordance with 40 CFR Part 763

Training Manager

11/29/23 Expiration Date

11/29/22
Date(s) of Course

11/29/2022

Examination Date

Course Location

Columbus, OH

33150 Lakeland Blvd. Cleveland, OH 44095 www.TSltraining.com

Course Certificare No.

22 TSI 418032 csr



Asbestos Building Inspector Refresher

Certificate

This is to certify

lace Hurt

XXX-XX-0133



section 855.120 of Title 77. IDPH recognition based on student request. (AHERA). The above student received the requisite training for asbestos accreditation under Title II of the Toxic Substances Control Act and State of Indiana requirements under 326 IAC 18-2 and Chapter 3745-22 Ohio Administrative Code. and the Illinois Department of Public Health (IDPH) under Refresher and has passed an examination in that course with a minimum score of 70% or better. Training was in accordance with 40 CFR Part 763 has attended and successfully completed the Asbestos Hazard Emergency Response Act mandatory course for the Asbestos Building Inspector

-	1
	9
	1
-	1
1	
1	30
1	
1	

11/30/23

11/30/22

11/30/2022

Columbus, OH

33150 Lakeland Blvd. Training Manager

www.TSltraining.com Cleveland, OH 44095

Expiration Date

Date(s) of Course

Examination Date

Course Location

Course Certificate No.

22 TSI 418147 ir



Asbestos Management Planner Refresher

Certificate

This is to certify

Jace Hurt

XXX-XX-0133



Refresher and has passed an examination in that course with a minimum score of 70% or better. Training was in accordance with 40 CFR Part 763 (AHERA). The above student received the requisite training for asbestos accreditation under Title II of the Toxic Substances Control Act and State of Indiana requirements under 326 IAC 18-2 and Chapter 3745-22 Ohio Administrative Code, and the Illinois Department of Public Health (IDPH) under section 855.120 of Title 77. IDPH recognition based on student request. has attended and successfully completed the Asbestos Hazard Emergency Response Act mandatory course for the Asbestos Management Planner

Course Location	Examination Date	Date(s) of Course	Expiration Date	rairing Manager
				T 76
Columbus, OH	11/30/2022	11/30/22	11/30/23	Less Color

33150 Lakeland Blvd. Cleveland, OH 44095 www.TSltraining.com

Course Certificate No.

22 TSI 418153 mpr



Asbestos Contractor Supervisor Refresher

Certificate

This is to certify

Jace Hurt

XXX-XX-0133



has attended and successfully completed the Asbestos Hazard Ernergency Response Act mandatory course for the Asbestos Contractor Supervisor section 855.120 of Title 77. IDPH recognition based on student request. Refresher and has passed an examination in that course with a minimum score of 70% or better. Training was in accordance with 40 CFR Part 763 Indiana requirements under 326 IAC 18-2, Chapter 3745-22 Ohio Administrative Code, and the Illinois Department of Public Health (IDPH) under (AHERA). The above student received the requisite training for asbestos accreditation under Title II of the Toxic Substances Control Act, State of

Course Location	Examination Date	Date(s) of Course	Expiration Date	I faining Manager
				H
Columbus, OH	11/29/2022	11/29/22	11/29/23	Las John
				ノノフロ

33150 Lakeland Blvd. Cleveland, OH 44095 vwww.TSltraining.com

Course Certificate No.

22 TSI 418034 csr